








F16. 1




F14.3A



F14 3B



F16.2



F1G.4

	500	. 50%	510
	Intensity	Gain	RMS
T_0	140	10	.05
T_1	0	10	0
T_2	0	10	0
•	•	•	· •
•	•	•.	•
•	•	•	•
T_{N}	140	10	.05
504			

F16.5